

.1

Recommended Service Bulletin SB-MD10-004

1 Technical Details

1.A Category

Mandatory

1.B Subject

Belly-Hook Release Cable Replacement

1.C Affected

Type: JS-MD Single
Model: JS-MD 3
Serial Numbers: 3.MD003 up to and including 3.MD092

1.D Reason

The integrity of the stop sleeve crimp on the belly-hook release cable is under suspicion. The concern was raised when the crimping process used for this particular crimp was scrutinized.

1.E Time of Compliance

This Service Bulletin must be accomplished within the next 3 months from the date of receipt OR during the next Annual Inspection, whichever comes first.

1.F Reference

/1/ MD10-WOI-53-001-R00 Work Instruction Belly-Hook Release Cable Replacement

1.G Mass and CG

Not affected

1.H Actions

- Replace Belly-Hook Release Cable

1.I Interchangeability and Mixability of Parts

None

1.J Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.603.

1.K Appendices

None

2 Remarks

2.A Remarks

None

3 Approval Signatures

Remark: With the signature the **HOA** confirms that the technical content of the Service Bulletin has been checked and the change described is approved.

(Head of Office of Airworthiness)	Approved by HOA
Initial Issue	