

Service Bulletin

EASA.21J.603

Doc.: SB-MD01-003 Date: 25.01.2022 Page: 1 of 3

Highly Recommended Service Bulletin

SB-MD01-003

1 Technical Details

1.A Category

Highly recommended

1.B Subject

Jet System Engine Fuel line replacement

1.C Affected

Type: JS-MD Single / Model: JS-MD 1C

SNs: All S/N with engine installed up to S/N 1C.MD123

1.D Reason

Improved fire-resistance in compliance with certification requirements regarding the fuel lines and rubber hoses on the engine side of the firewall.

1.E Time of Compliance

With the next annual inspection or when 8 year replacement of start line and fuel line rubber is due, whichever comes first.

1.F Reference

- /1/ MD01-WOI-28-001 Work Instruction Jet System Engine Fuel line replacement
- /2/ MD01-AMM-00-002 JS-MD 1C Jet Sustainer Maintenance Manual Supplement

1.G Mass and CG

No change in mass and CG.

1.H Actions

Perform the actions, set forth in MD01-WOI-28-001 (Ref. /1/) with reference to the JS-MD 1C Jet Sustainer Maintenance Manual Supplement MD01-AMM-00-002 (Ref. /2/).

1.I Interchangeability and Mixability of Parts

None.

1.J Approval

The technical content of this document is approved under the authority of the DOA ref. EASA.21J.603.



Service Bulletin

EASA.21J.603

Doc.: SB-MD01-003 Date: 25.01.2022 Page: 2 of 3

1.K Appendices

None.

2 Planning Information

2.A Material

The following parts are required for the service bulletin and must be purchased from M&D Flugzeugbau:

Non-standard parts:

- Start line assembly 1B-4.11.01 v4
- Fuel line assembly 1B-4.12.01 v4

Standard parts:

- Fuel line fire sleeve 1 1B-4.13.06
- Fuel line fire sleeve 2 1B-4.13.04
- Start line fire sleeve 1 1B-4.13.05
- Start line fire sleeve 2 1B-4.13.02

2.B Special Tools

Turbine Tool software and USB cable

3 Remarks

The installation and release to service by certifying staff must only be accomplished by M&D Flugzeugbau or by a maintenance organisation according to European Union Commission Regulation (EU) 1321/2014. In countries outside the scope of EU 1321/2014 the corresponding national rules shall apply.

Only original spare parts may be used. Parts (other than standard parts) and material kits may only be installed if an EASA Form 1 is issued for these products. For standard parts the invoice from M&D Flugzeugbau is valid as a certificate of conformity.

Work instruction and Parts can be obtained from

M&D Flugzeugbau GmbH & Co. KG Streeker Straße 5B 26446 / Friedeburg

Phone: +49 44 65 97878 0 / Fax: +49 44 65 97878 99

E-Mail: info@md-flugzeugbau.de

Please indicate S/N and operating time of your aircraft in your inquiry.



Service Bulletin

EASA.21J.603

Doc.: SB-MD01-003 **Date:** 25.01.2022 **Page:** 3 of 3

4 Approval Signatures

Remark: With the signature the **HOA** confirms that the technical content of the Service Bulletin has been checked and the change described is approved.

	Approved by HOA
(Head of Office of Airworthiness)	on: 25.01.2022 under approval No.: MCA-2020-013-R00
Initial Issue	

Form: MD-21J-FO-CAW-001, Rev.: 00