

Service Bulletin

EASA.21J.603

Doc.: SB-MD10-002 Date: 03.08.2020 Page: 1 of 3

Recommended Service Bulletin

SB-MD10-002

1 Technical Details

1.A Category

Recommended

1.B Subject

Tip Drain & Filling Cap Installation

1.C Affected

All JS-MD Single / Model JS-MD 3 up to and including S/N MD.079

1.D Reason

Enable improved drying of the integral tanks in the 18m wing tips and easier filling of the wing tips.

1.E Time of Compliance

N/A

1.F Reference

/1/ MD10-WOI-41-001 Work Instruction Tip Ventilation Upgrade

/2/ MCA-2020-008

1.G Mass and CG

Not affected.

1.H Actions

Installation of drain/filler cap sleeve assembly according to Work Instruction, see Ref. /1/.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this SB.

1.I Interchangeability and Mixability of Parts

None.

1.J Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.603.

1.K Appendices

None.



Service Bulletin

EASA.21J.603

Doc.: SB-MD10-002 Date: 03.08.2020 Page: 2 of 3

2 Planning Information

2.A Material

To be purchased from M&D Flugzeugbau:

- 4x Tank Sleeves (P/N 232 11 041 00)
- 2x Drain cap (P/N 232 11 042 00)
- 2x Filler cap (P/N 232 11 005 00)
- 4x O-Ring (P/N 108 02 007 00)
- DXF Files (Optional for marking jigs)

Standard Materials:

- Resin: MGS L285 with Hardener H285
- Release Agent, e.g. wax-based mould release agent
- Cotton Flocks
- CAB-O-SIL
- Superwood; Thickness:6mm (Optional if marking jigs are required; cuts can be obtained from M&D)
- Sandpaper (several grades)
- Pipe or rod, Ø19.5mm (optional for marking jigs)

2.B Special Tools

Hole Saw suitable for CFRP. sizes as follows

- 27mm
- 38mm

3 Remarks

All actions have to be inspected as complex maintenance by certifying staff according to M.A.801 (EC 1321/2014) and have to be certified in the sailplane inspection documents and in the sailplane logbook.

This SB is only applicable if a Release to Maintenance exists, which specifies type and S/N of the aircraft. The Release to Maintenance must be requested from the type certificate holder (M&D Flugzeugbau).

Only original spare parts may be used. Parts (other than standard parts) and material kits may only be installed if an EASA Form 1 is issued for these products. For standard parts the invoice from M&D Flugzeugbau is valid as a certificate of conformity.

Work instruction and Parts can be obtained from

M&D Flugzeugbau GmbH & Co. KG Streeker Straße 5B 26446 / Friedeburg

Phone: +49 44 65 97878 0 / Fax: +49 44 65 97878 99

E-Mail: info@md-flugzeugbau.de

Please indicate S/N and operating time of your aircraft in your inquiry.

Form: MD-21J-FO-CAW-001, Rev.: 00



Service Bulletin

EASA.21J.603

Doc.: SB-MD10-002 **Date:** 03.08.2020 **Page:** 3 of 3

4 Approval Signatures

Remark: With the signature the **HOA** confirms that the technical content of the Service Bulletin has been checked and the change described is approved.

	Approved by HOA
(Head of Office of Airworthiness)	on: 03.06.2020 under approval No.: MCA-2020-008
Initial Issue	

Form: MD-21J-FO-CAW-001, Rev.: 00